



Figure:1 Sillegadha site staff quarter building slab and roof beam shuttering work



Figure:2 Sillegadha site staff quarter building slab reinforcement work



Figure:3 Sillegadha site staff quarter building roof slab and staircase shuttering and reinforcement work



Figure:4 Sillegadha site staff quarter building



Figure:5 Sillegadha site staff quarter building slab concreting work




Figure: 6 Performing joint measurement of Sillegadha site staff quarter building slab and staircase



Figure:7 Sillegadha site staff quarter building staircase first flight concreting work



Figur:8 Sillegadha site staff quarter building brick work (on grid A-A , C-C ,1-1 and 6-6) up to plinth level from plinth beam top